

2020

ORJ

**Bi Annual (2<sup>nd</sup>) ANSUL and  
RANGEGUARD Suppression  
System Testing Report**

11-13-2020

# Hood Fire Suppression System Inspection Report



**PROTEGIS**  
F I R E S A F E T Y

**Location Code:** CDUFIXM

**Contact:** Sgt Weitzel

**Contact Address:** 1201 ORIENT RD, 1201 ORIENT RD  
TAMPA, FL 33619-3325

**Phone:** 813 247 0294

**Email:**

**Property Evaluated:** Orient Road Jail Facility (Detention and  
Correctional)

1201 ORIENT RD, 1201 ORIENT RD  
TAMPA, FL 33619-3325

**Description:** Hood (Kitchen 1)

**Company:** Protegis Fire & Safety

**Address:** 2801 East S.R. 60  
Valrico, FL 33594

**Company Phone:** 877-662-3473

**Inspector:** CHRIS LETO  
FEP20-000056

**Date of Work:** 11/13/2020

**Frequency:** Semi-Annual

---

## Attached Files

There are no attachments for this submission

---

## Deficiency Summary

**Status:** Open

**Severity:** Non-Critical

**Question-35**

35. Did fire alarm actuate as intended?

FIRE ALARM DIDN'T SOUND AS REQUIRED.

**Status:** Open

**Severity:** Non-Critical

**Question-36**

36. Were there any deficiencies found during this inspection?

FORE ALARM DID NOT SOUND AS REQUIRED.

---

## General Comments

There are no general comments for this submission



**PROTEGIS**  
FIRE & SAFETY

Protegis Fire & Safety  
2801 East S.R. 60  
Valrico, FL 33594  
Phone: 877-662-3473

## Hood Fire Suppression System Inspection Report

### Account Information

Facility Name: Orient Road Jail Facility	Property Type: Detention and Correctional	Assembly Description: Hood (Kitchen 1)
Service Address: 1201 ORIENT RD, 1201 ORIENT RD, TAMPA, FL, 33619-3325		
Mailing Name: Srgt Weitzel		Phone: 813 247 0294
Mailing Address: 1201 ORIENT RD, 1201 ORIENT RD, TAMPA, FL, 33619-3325		

### Hood Inspection Information

Serial # S073609	Mfg Ansul	Model R102
<input type="checkbox"/> Recharge	<input type="checkbox"/> Install	<input type="checkbox"/> Repipe
<input type="checkbox"/> Hydro	<input checked="" type="checkbox"/> Wet	<input type="checkbox"/> Dry
Other		
Location Of Cylinder Kitchen		Mfg. Manual Ansul
Master Cyl. Size 3gallon	Slave Size 3gallon	Slave Size 3gallon
Mfg. Date 2004	Hydro. Date 2017	Last Recharge 2017
Fuel Shut Off <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	Electric <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	Gas <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
Size 1.5"	360° Links 9	
450° Links	500° Links	
Duct Size(s) 16x 16	Plenum Size(s) 16ft x 17	
Other Links		

### Appliances (Left to Right)

double convection oven
6 BURNER RANGE 36"x24"
GRIDDLE 36"x 24"
FRYER 15"x13"
Tilt SKILLET 31"x26"
TILT SKILLET 28"x41"
Steam kettle
PRESSURE COOKER

1. All appliances properly covered w/correct nozzles?  
☒ Yes ☐ No ☐ N/A
3. Checked positioning of all nozzles?  
☒ Yes ☐ No ☐ N/A
5. Hood/duct penetrations sealed w/weld or UL device?  
☒ Yes ☐ No ☐ N/A
7. If system discharged are seals broken?  
☐ Yes ☐ No ☒ N/A
9. Checked cartridge weight?  
☒ Yes ☐ No ☐ N/A
11. Operate system from terminal link?  
☒ Yes ☐ No ☐ N/A
13. Checked micro switch operation?  
☒ Yes ☐ No ☐ N/A

2. Duct and plenum covered w/correct nozzles?  
☒ Yes ☐ No ☐ N/A
4. System installed in accordance w/mfg. UL listing?  
☒ Yes ☐ No ☐ N/A
6. Seals intact no evidence of tampering?  
☒ Yes ☐ No ☐ N/A
8. Pressure gauge in proper range?  
☐ Yes ☐ No ☒ N/A
10. Inspected cylinder and mounting brackets?  
☒ Yes ☐ No ☐ N/A
12. Tested for proper operation from remote?  
☒ Yes ☐ No ☐ N/A
14. Checked operation of gas valve?  
☒ Yes ☐ No ☐ N/A



**PROTEGIS**  
F I R E & S A F E T Y

Protegis Fire & Safety  
2801 East S.R. 60  
Valrico, FL 33594  
Phone: 877-662-3473

15. Clean nozzles?  
☒ Yes ☐ No ☐ N/A

17. Replaced links?  
☒ Yes ☐ No ☐ N/A

19. Piping and conduit securely bracketed?  
☒ Yes ☐ No ☐ N/A

21. Proper clearance flame to filters?  
☒ Yes ☐ No ☐ N/A

23. All filters put back in place?  
☒ Yes ☐ No ☐ N/A

25. Manual and remote set/seals in place?  
☒ Yes ☐ No ☐ N/A

27. System operation and seals in place?  
☒ Yes ☐ No ☐ N/A

29. Clean cylinder and mount?  
☒ Yes ☐ No ☐ N/A

31. Personnel instructed on system operation?  
☒ Yes ☐ No ☐ N/A

33. Extinguishers properly serviced?  
☒ Yes ☐ No ☐ N/A

35. Did fire alarm actuate as intended?  
☐ Yes ☒ No ☐ N/A

16. Proper nozzle covers in place?  
☒ Yes ☐ No ☐ N/A

18. Checked travel of cable nuts/s-hooks?  
☒ Yes ☐ No ☐ N/A

20. Proper separation between fryers and flame?  
☒ Yes ☐ No ☐ N/A

22. Exhaust fan operating?  
☒ Yes ☐ No ☐ N/A

24. Fuel shut-off in on position?  
☒ Yes ☐ No ☐ N/A

26. Replaced system covers?  
☒ Yes ☐ No ☐ N/A

28. Slave cylinder operational?  
☒ Yes ☐ No ☐ N/A

30. Fan warning on hood?  
☒ Yes ☐ No ☐ N/A

32. Proper hand portable extinguisher?  
☒ Yes ☐ No ☐ N/A

34. Service and certification tag on system?  
☒ Yes ☐ No ☐ N/A

36. Were there any deficiencies found during this inspection?  
☒ Yes ☐ No ☐ N/A

**Explanation of "No" Answers**

Any "No" answers must be explained using the comment specific for each question. Additional comments can be added here.  
Please see the summary section at the top of the form for the comments.

☐ System is installed in accordance with manufacturers instruction NFPA 17 or 17A and or 96 sections applicable to fire suppression systems only.  
Florida regulations 69A-21 and 633.

☒ The pre-engineered state certified fire systems tech. certifies that he personally inspected and surveyed the system and has found the conditions to be as stated on this report. This system did not pass survey. Warning: Failure to correct all deficiencies may cause loss of life and or property. See Deficiency Summary Section.

**Tester Information**

Frequency:  
Semi-Annual

Inspected By:  
CHRIS LETO

Date of Test:  
11/13/2020

Tester Signature:

Certification Number:  
FEP20-000056

Customer Signature:

R. Bargholz

Customer Name:  
R Bargholz

# Hood Fire Suppression System Inspection Report



**PROTEGIS**  
FIRE & SAFETY

**Location Code:** CDUFIXM

**Contact:** Srgt Weitzel

**Contact Address:** 1201 ORIENT RD, 1201 ORIENT RD  
TAMPA, FL 33619-3325

**Phone:** 813 247 0294

**Email:**

**Property Evaluated:** Orient Road Jail Facility (Detention and  
Correctional)

1201 ORIENT RD, 1201 ORIENT RD  
TAMPA, FL 33619-3325

**Description:** Hood (Kitchen 2)

**Company:** Protegis Fire & Safety

**Address:** 2801 East S.R. 60  
Valrico, FL 33594

**Company Phone:** 877-662-3473

**Inspector:** CHRIS LETO  
FEP20-000056

**Date of Work:** 11/13/2020

**Frequency:** Semi-Annual

---

## Attached Files

There are no attachments for this submission

---

## Deficiency Summary

There are no reported deficiencies for this submission

---

## General Comments

There are no general comments for this submission



Protegis Fire & Safety  
2801 East S.R. 60  
Valrico, FL 33594  
Phone: 877-662-3473

## Hood Fire Suppression System Inspection Report

### Account Information

Facility Name: Orient Road Jail Facility	Property Type: Detention and Correctional	Assembly Description: Hood (Kitchen 2)
Service Address: 1201 ORIENT RD, 1201 ORIENT RD, TAMPA, FL, 33619-3325		
Mailing Name: Srgt Weitzel		Phone: 813 247 0294
Mailing Address: 1201 ORIENT RD, 1201 ORIENT RD, TAMPA, FL, 33619-3325		

### Hood Inspection Information

Serial # TBC 024366	Mfg Range Guard	Model WHDR
<input type="checkbox"/> Recharge	<input type="checkbox"/> Install	<input type="checkbox"/> Repipe
<input type="checkbox"/> Hydro		<input checked="" type="checkbox"/> Wet
<input type="checkbox"/> Dry		
Location Of Cylinder Kitchen		
Master Cyl. Size 4 gallon	Slave Size 2.5 gallon	Slave Size 2.5 gallon
Mfg. Manual Range Guard	Mfg. Date 2003	Hydro. Date 2017
Last Recharge 2017		
Fuel Shut Off <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A	Electric <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	Gas <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
Size na	360° Links 4	450° Links
500° Links	Other Links	
Duct Size(s) 16 x 16	Plenum Size(s) 16ft x 17	

### Appliances (Left to Right)

kettle
kettle
kettle

1. All appliances properly covered w/correct nozzles?  
☒ Yes ☐ No ☐ N/A
2. Duct and plenum covered w/correct nozzles?  
☒ Yes ☐ No ☐ N/A
3. Checked positioning of all nozzles?  
☒ Yes ☐ No ☐ N/A
4. System installed in accordance w/mfg. UL listing?  
☒ Yes ☐ No ☐ N/A
5. Hood/duct penetrations sealed w/weld or UL device?  
☒ Yes ☐ No ☐ N/A
6. Seals intact no evidence of tampering?  
☒ Yes ☐ No ☐ N/A
7. If system discharged are seals broken?  
☐ Yes ☐ No ☒ N/A
8. Pressure gauge in proper range?  
☒ Yes ☐ No ☐ N/A
9. Checked cartridge weight?  
☒ Yes ☐ No ☐ N/A
10. Inspected cylinder and mounting brackets?  
☒ Yes ☐ No ☐ N/A
11. Operate system from terminal link?  
☒ Yes ☐ No ☐ N/A
12. Tested for proper operation from remote?  
☒ Yes ☐ No ☐ N/A
13. Checked micro switch operation?  
☒ Yes ☐ No ☐ N/A
14. Checked operation of gas valve?  
☒ Yes ☐ No ☐ N/A
15. Clean nozzles?  
☒ Yes ☐ No ☐ N/A
16. Proper nozzle covers in place?  
☒ Yes ☐ No ☐ N/A
17. Replaced links?  
☒ Yes ☐ No ☐ N/A
18. Checked travel of cable nuts/s-hooks?  
☒ Yes ☐ No ☐ N/A
19. Piping and conduit securely bracketed?  
☒ Yes ☐ No ☐ N/A
20. Proper separation between fryers and flame?  
☐ Yes ☐ No ☒ N/A



**PROTEGIS**  
FIRE & SAFETY

Protegis Fire & Safety

2801 East S.R. 60

Valrico, FL 33594

Phone: 877-662-3473

21. Proper clearance flame to filters?

☐ Yes ☐ No ☒ N/A

23. All filters put back in place?

☒ Yes ☐ No ☐ N/A

25. Manual and remote set/seals in place?

☒ Yes ☐ No ☐ N/A

27. System operation and seals in place?

☒ Yes ☐ No ☐ N/A

29. Clean cylinder and mount?

☒ Yes ☐ No ☐ N/A

31. Personnel instructed on system operation?

☒ Yes ☐ No ☐ N/A

33. Extinguishers properly serviced?

☒ Yes ☐ No ☐ N/A

35. Did fire alarm actuate as intended?

☒ Yes ☐ No ☐ N/A

**Explanation of "No" Answers**

Any "No" answers must be explained using the comment specific for each question. Additional comments can be added here.  
Please see the summary section at the top of the form for the comments.

☒ System is installed in accordance with manufacturers instruction NFPA 17 or 17A and or 96 sections applicable to fire suppression systems only.  
Florida regulations 69A-21 and 633.

The pre-engineered state certified fire systems tech. certifies that he personally inspected and surveyed the system and has found the conditions to be as stated on this report. This system did not pass survey. Warning: Failure to correct all deficiencies may cause loss of life and or property. See Deficiency Summary Section.

**Tester Information**

Frequency:  
Semi-Annual

Inspected By:  
CHRIS LETO

Date of Test:  
11/13/2020

Tester Signature:

Certification Number:  
FEP20-000056

Customer Signature:

Customer Name:  
R Bargholz

2020

FRJ

**Bi Annual (2<sup>nd</sup>) Kitchen Hood  
Suppression System Testing  
Report**

11-13-2020





PROTEGIS

Ph: 813-662-3473 Fax: 813-655-5456

Professional, Proactive, Protection

Cust #: C13086

Loc #: FS129716

Invoice#:

W.O.#: 104484 ✓

Date: 11/12/2020

P.O.#:

Bill To:

Address:

Ph:

City:

State:

Zip:

Service Site Name: Faulkenburg Jail

Service Address: 520 N. Faulkenburg Rd

Ph: 813-247-0231

City: Tampa

State: FL

Zip: 33619

Authorized By (PRINT) Robert Bargholz

Service Tech: Chris

Visa	Master Card	#	Check#	Annual	Svc Call	Web Order	Walk-In	New ACCT.
Cash	Net 10 Days				Semi-Annual	Qty	Monthly	Weekly
QTY.	Description	Unit Price	Amount		QTY.	Description	Unit Price	Amount
	Annual Maint.					New 2.5lb Exting		
	Tamper Seal					New 5lb Exting		
	Lock Pin					New 10lb Exting		
	5lb. Rech					New 20lb Exting		
	10lb. Rech					New Exting		
	20lb. Rech					New Exting		
	5 Year Maint.					New Exting		
	Rebuild Kit					Fire Suppression Sys. Insp.	150.00	750.00
	Band & Clip					Fusible Links		
	Handle					Signs		
	Bracket					Hydrostatic Test		
	Sign Part #					Recharge Other		
	Cover					Emergency Light Insp		
	Cabinet #					Exit Light Insp.		
1	SCA1	375.00	375.00			Batteries		
						Bulbs		
						Labor		

Comments:

State Required Serial Numbers

DOT/FMPR

\$ 42.50

Freight

Service Charge

Subtotal

1075.00

Tax No. or Tax

Amount Due \$

1075.00

IN THE EVENT IT BECOMES NECESSARY TO PLACE THE INDEBTEDNESS CREATED BY THIS INVOICE FOR COLLECTION, PURCHASER AGREES TO PAY ALL REASONABLE COST FOR COLLECTION INCLUDING ATTORNEY'S FEES A SERVICE CHARGE OF 2% MONTHLY 22% ANNUALLY WILL BE APPLIED ON UNPAID BALANCE OVER 30 DAYS NOTICE: AFTER 30 DAYS PAST DUE, A \$20.00 LATE FEE WILL BE CHARGE FOR MONTHLY PROCESSING Shop Address: 2801 East SR 80 Vero, Florida 33594

Authorized Signature:

x Robert Bargholz

CALL AND ASK ABOUT OUR COMPLETE FIRE PROTECTION SERVICES  
LIC: FPC 20-000006 FPC 20-000007 EF-20000861 FED 20-000008 FED 20-000009

# Hood Fire Suppression System Inspection Report



**PROTEGIS**

**Location Code:** PMNPSQS

**Contact:** Jon Wietzel

**Contact Address:** 520 N FALKENBURG RD  
TAMPA, FL 33619-7884

**Phone:** 813-247-8074

**Email:**

**Property Evaluated:** Falkenburg Rd Jail (Detention and  
Correctional)

520 N FALKENBURG RD  
TAMPA, FL 33619-7884

**Description:** Hood (BUCKEYE #1)

**Company:** Protegis Fire & Safety

**Address:** 2801 East S.R. 60  
Valrico, FL 33594

**Company Phone:** 877-662-3473

**Inspector:** CHRIS LETO  
FEP20-000056

**Date of Work:** 11/13/2020

**Frequency:** Semi-Annual

---

## Attached Files

There are no attachments for this submission

---

## Deficiency Summary

There are no reported deficiencies for this submission

---

## General Comments

There are no general comments for this submission



**PROTEGIS**  
FIRE & SAFETY

Protegis Fire & Safety  
2801 East S.R. 60  
Valrico, FL 33594  
Phone: 877-662-3473

## Hood Fire Suppression System Inspection Report

### Account Information

Facility Name: Falkenburg Rd Jail	Property Type: Detention and Correctional	Assembly Description: Hood (BUCKEYE #4&5)
Service Address: 520 N FALKENBURG RD, TAMPA, FL, 33619-7884		
Mailing Name: Jon Wietzel	Phone: 813-247-8074	
Mailing Address: 520 N FALKENBURG RD, TAMPA, FL, 33619-7884		

### Hood Inspection Information

Serial # 12610FR/4813FS	Mfg BUCKEYE	Model BFR
<input type="checkbox"/> Recharge	<input type="checkbox"/> Install	<input type="checkbox"/> Repipe
<input type="checkbox"/> Hydro	<input checked="" type="checkbox"/> Wet	<input type="checkbox"/> Dry
Location Of Cylinder IN CEILING ABOVE HOOD		
Master Cyl. Size BFR 20	Slave Size BFR 15	Slave Size Na
Mfg. Manual BFR	Mfg. Date 2017	Hydro. Date Na
Fuel Shut Off <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	Electric <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	Gas <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
360° Links 8	450° Links	500° Links
Duct Size(s) 12 x 11 (4)	Plenum Size(s) 8' 3" x 16 (4)	Other Links

### Appliances (Left to Right)

kettle (2)
Double steamer
tilt skillet 44 x 24 (3)

1. All appliances properly covered w/correct nozzles?  
☒ Yes ☐ No ☐ N/A
2. Duct and plenum covered w/correct nozzles?  
☒ Yes ☐ No ☐ N/A
3. Checked positioning of all nozzles?  
☒ Yes ☐ No ☐ N/A
4. System installed in accordance w/mfg. UL listing?  
☒ Yes ☐ No ☐ N/A
5. Hood/duct penetrations sealed w/weld or UL device?  
☒ Yes ☐ No ☐ N/A
6. Seals intact no evidence of tampering?  
☒ Yes ☐ No ☐ N/A
7. If system discharged are seals broken?  
☐ Yes ☐ No ☒ N/A
8. Pressure gauge in proper range?  
☒ Yes ☐ No ☐ N/A
9. Checked cartridge weight?  
☒ Yes ☐ No ☐ N/A
10. Inspected cylinder and mounting brackets?  
☒ Yes ☐ No ☐ N/A
11. Operate system from terminal link?  
☒ Yes ☐ No ☐ N/A
12. Tested for proper operation from remote?  
☒ Yes ☐ No ☐ N/A
13. Checked micro switch operation?  
☒ Yes ☐ No ☐ N/A
14. Checked operation of gas valve?  
☒ Yes ☐ No ☐ N/A
15. Clean nozzles?  
☒ Yes ☐ No ☐ N/A
16. Proper nozzle covers in place?  
☒ Yes ☐ No ☐ N/A
17. Replaced links?  
☒ Yes ☐ No ☐ N/A
18. Checked travel of cable nuts/s-hooks?  
☒ Yes ☐ No ☐ N/A
19. Piping and conduit securely bracketed?  
☒ Yes ☐ No ☐ N/A
20. Proper separation between fryers and flame?  
☐ Yes ☐ No ☒ N/A



**PROTEGIS**  
FIRE FE

Protegis Fire & Safety  
2801 East S.R. 60  
Valrico, FL 33594  
Phone: 877-662-3473

21. Proper clearance flame to filters?  
☐ Yes ☐ No ☒ N/A
22. Exhaust fan operating?  
☒ Yes ☐ No ☐ N/A
23. All filters put back in place?  
☒ Yes ☐ No ☐ N/A
24. Fuel shut-off in on position?  
☒ Yes ☐ No ☐ N/A
25. Manual and remote set/seals in place?  
☒ Yes ☐ No ☐ N/A
26. Replaced system covers?  
☒ Yes ☐ No ☐ N/A
27. System operation and seals in place?  
☒ Yes ☐ No ☐ N/A
28. Slave cylinder operational?  
☒ Yes ☐ No ☐ N/A
29. Clean cylinder and mount?  
☒ Yes ☐ No ☐ N/A
30. Fan warning on hood?  
☒ Yes ☐ No ☐ N/A
31. Personnel instructed on system operation?  
☒ Yes ☐ No ☐ N/A
32. Proper hand portable extinguisher?  
☒ Yes ☐ No ☐ N/A
33. Extinguishers properly serviced?  
☒ Yes ☐ No ☐ N/A
34. Service and certification tag on system?  
☒ Yes ☐ No ☐ N/A
35. Did fire alarm actuate as intended?  
☒ Yes ☐ No ☐ N/A
36. Were there any deficiencies found during this inspection?  
☐ Yes ☒ No ☐ N/A

**Explanation of "No" Answers**

Any "No" answers must be explained using the comment specific for each question. Additional comments can be added here.  
Please see the summary section at the top of the form for the comments.

- ☒ System is installed in accordance with manufacturers instruction NFPA 17 or 17A and or 96 sections applicable to fire suppression systems only.  
Florida regulations 69A-21 and 633.
- ☐ The pre-engineered state certified fire systems tech. certifies that he personally inspected and surveyed the system and has found the conditions to be as stated on this report. This system did not pass survey. Warning: Failure to correct all deficiencies may cause loss of life and or property. See Deficiency Summary Section.

**Tester Information**

Frequency:  
Semi-Annual

Inspected By:  
CHRIS LETO

Date of Test:  
11/13/2020

Tester Signature:

Certification Number:  
FEP20-000056

Customer Signature:

Customer Name:  
Robert Bargholz

# Hood Fire Suppression System Inspection Report



**PROTEGIS**  
IR & SAFETY

**Location Code:** PMNPSQS

**Contact:** Jon Wietzel

**Contact Address:** 520 N FALKENBURG RD  
TAMPA, FL 33619-7884

**Phone:** 813-247-8074

**Email:**

**Property Evaluated:** Falkenburg Rd Jail (Detention and  
Correctional)

520 N FALKENBURG RD  
TAMPA, FL 33619-7884

**Description:** Hood (BUCKEYE #2)

**Company:** Protegis Fire & Safety

**Address:** 2801 East S.R. 60  
Valrico, FL 33594

**Company Phone:** 877-662-3473

**Inspector:** CHRIS LETO  
FEP20-000056

**Date of Work:** 11/13/2020

**Frequency:** Semi-Annual

---

## Attached Files

There are no attachments for this submission

---

## Deficiency Summary

There are no reported deficiencies for this submission

---

## General Comments

There are no general comments for this submission



**PROTEGIS**  
FIRE & SAFETY

Protegis Fire & Safety  
2801 East S.R. 60  
Valrico, FL 33594  
Phone: 877-662-3473

## Hood Fire Suppression System Inspection Report

### Account Information

Facility Name: Falkenburg Rd Jail	Property Type: Detention and Correctional	Assembly Description: Hood (BUCKEYE #1)
Service Address: 520 N FALKENBURG RD, TAMPA, FL, 33619-7884		
Mailing Name: Jon Wietzel	Phone: 813-247-8074	
Mailing Address: 520 N FALKENBURG RD, TAMPA, FL, 33619-7884		

### Hood Inspection Information

Serial # 27471FO	Mfg BUCKEYE	Model BFR 10
<input type="checkbox"/> Recharge	<input type="checkbox"/> Install	<input type="checkbox"/> Repipe
<input type="checkbox"/> Hydro	<input checked="" type="checkbox"/> Wet	<input type="checkbox"/> Dry
Other		
Location Of Cylinder IN CEILING ABOVE HOOD		
Master Cyl. Size BFR 10	Slave Size BFR-5	Slave Size Na
Mfg. Manual BFR	Mfg. Date 2017	Hydro. Date Na
Fuel Shut Off <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	Electric <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	Last Recharge Na
Gas <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	Size Na	
360° Links 4	450° Links	500° Links
Duct Size(s) 12 x 8 (4)	Plenum Size(s) 11' 16" (2) & 7' 7" x 16" (2)	Other Links

### Appliances (Left to Right)

kettle x 4

1. All appliances properly covered w/correct nozzles?  
☒ Yes ☐ No ☐ N/A
2. Duct and plenum covered w/correct nozzles?  
☒ Yes ☐ No ☐ N/A
3. Checked positioning of all nozzles?  
☒ Yes ☐ No ☐ N/A
4. System installed in accordance w/mfg. UL listing?  
☒ Yes ☐ No ☐ N/A
5. Hood/duct penetrations sealed w/weld or UL device?  
☒ Yes ☐ No ☐ N/A
6. Seals intact no evidence of tampering?  
☒ Yes ☐ No ☐ N/A
7. If system discharged are seals broken?  
☐ Yes ☒ No ☐ N/A
8. Pressure gauge in proper range?  
☒ Yes ☐ No ☐ N/A
9. Checked cartridge weight?  
☒ Yes ☐ No ☐ N/A
10. Inspected cylinder and mounting brackets?  
☒ Yes ☐ No ☐ N/A
11. Operate system from terminal link?  
☒ Yes ☐ No ☐ N/A
12. Tested for proper operation from remote?  
☒ Yes ☐ No ☐ N/A
13. Checked micro switch operation?  
☒ Yes ☐ No ☐ N/A
14. Checked operation of gas valve?  
☒ Yes ☐ No ☐ N/A
15. Clean nozzles?  
☒ Yes ☐ No ☐ N/A
16. Proper nozzle covers in place?  
☒ Yes ☐ No ☐ N/A
17. Replaced links?  
☒ Yes ☐ No ☐ N/A
18. Checked travel of cable nuts/s-hooks?  
☒ Yes ☐ No ☐ N/A
19. Piping and conduit securely bracketed?  
☒ Yes ☐ No ☐ N/A
20. Proper separation between fryers and flame?  
☐ Yes ☐ No ☒ N/A
21. Proper clearance flame to filters?  
☐ Yes ☐ No ☒ N/A
22. Exhaust fan operating?  
☒ Yes ☐ No ☐ N/A
23. All filters put back in place?
24. Fuel shut-off in on position?



**PROTEGIS**  
E S F E Y

Protegis Fire & Safety  
2801 East S.R. 60  
Valrico, FL 33594  
Phone: 877-662-3473

☒ Yes ☐ No ☐ N/A

25. Manual and remote set/seals in place?

☒ Yes ☐ No ☐ N/A

27. System operation and seals in place?

☒ Yes ☐ No ☐ N/A

29. Clean cylinder and mount?

☒ Yes ☐ No ☐ N/A

31. Personnel instructed on system operation?

☒ Yes ☐ No ☐ N/A

33. Extinguishers properly serviced?

☒ Yes ☐ No ☐ N/A

35. Did fire alarm actuate as intended?

☒ Yes ☐ No ☐ N/A

**Explanation of "No" Answers**

Any "No" answers must be explained using the comment specific for each question. Additional comments can be added here.  
Please see the summary section at the top of the form for the comments.

☒ System is installed in accordance with manufacturers instruction NFPA 17 or 17A and or 96 sections applicable to fire suppression systems only.  
Florida regulations 69A-21 and 633.

☐ The pre-engineered state certified fire systems tech. certifies that he personally inspected and surveyed the system and has found the conditions to be as stated on this report. This system did not pass survey. Warning: Failure to correct all deficiencies may cause loss of life and or property. See Deficiency Summary Section.

**Tester Information**

Frequency:  
Semi-Annual

Inspected By:  
CHRIS LETO

Date of Test:  
11/13/2020

Tester Signature:

Certification Number:  
FEP20-000056

Customer Signature:

Customer Name:  
Robert Bargholz

# Hood Fire Suppression System Inspection Report



# PROTEGIS

**Location Code:** PMNPSQS

**Contact:** Jon Wietzel

**Contact Address:** 520 N FALKENBURG RD  
TAMPA, FL 33619-7884

**Phone:** 813-247-8074

**Email:**

**Property Evaluated:** Falkenburg Rd Jail (Detention and  
Correctional)

520 N FALKENBURG RD  
TAMPA, FL 33619-7884

**Description:** Hood (BUCKEYE #3)

**Company:** Protegis Fire & Safety

**Address:** 2801 East S.R. 60  
Valrico, FL 33594

**Company Phone:** 877-662-3473

**Inspector:** CHRIS LETO  
FEP20-000056

**Date of Work:** 11/13/2020

**Frequency:** Semi-Annual

---

## Attached Files

There are no attachments for this submission

---

## Deficiency Summary

There are no reported deficiencies for this submission

---

## General Comments

There are no general comments for this submission





**PROTEGIS**  
F E T

Protegis Fire & Safety  
2801 East S.R. 60  
Valrico, FL 33594  
Phone: 877-662-3473

## Hood Fire Suppression System Inspection Report

### Account Information

Facility Name:  
Falkenburg Rd Jail

Property Type:  
Detention and Correctional

Assembly Description:  
Hood (BUCKEYE #3)

Service Address:  
520 N FALKENBURG RD, TAMPA, FL, 33619-7884

Mailing Name:  
Jon Wietzel

Phone:  
813-247-8074

Mailing Address:  
520 N FALKENBURG RD, TAMPA, FL, 33619-7884

### Hood Inspection Information

Serial #  
27471FQ

Mfg  
BUCKEYE

Model  
BFR 10

☐ Recharge

☐ Install

☐ Repipe

☐ Hydro

☒ Wet

☐ Dry

Other

Location Of Cylinder  
IN CEILING ABOVE HOOD

Mfg. Manual  
BFR

Master Cyl. Size  
BFR 10

Slave Size  
Na

Slave Size  
Na

Mfg. Date  
2017

Hydro. Date  
na

Last Recharge  
na

Fuel Shut Off  
☒ Yes ☐ No ☐ N/A

Electric  
☒ Yes ☐ No ☐ N/A

Gas  
☒ Yes ☐ No ☐ N/A

Size  
1.5"

360° Links

450° Links  
3

500° Links

Other Links

Duct Size(s)  
12 x 11 (2)

Plenum Size(s)  
7ft x 16 (2)

### Appliances (Left to Right)

Double convection oven x2

six burner 36 x 24

GRIDDLE 48 x 24

fryer 14 x 14

1. All appliances properly covered w/correct nozzles?  
☒ Yes ☐ No ☐ N/A

3. Checked positioning of all nozzles?  
☒ Yes ☐ No ☐ N/A

5. Hood/duct penetrations sealed w/weld or UL device?  
☒ Yes ☐ No ☐ N/A

7. If system discharged arc seals broken?  
☐ Yes ☐ No ☒ N/A

9. Checked cartridge weight?  
☒ Yes ☐ No ☐ N/A

11. Operate system from terminal link?  
☒ Yes ☐ No ☐ N/A

13. Checked micro switch operation?  
☒ Yes ☐ No ☐ N/A

15. Clean nozzles?  
☒ Yes ☐ No ☐ N/A

17. Replaced links?  
☒ Yes ☐ No ☐ N/A

19. Piping and conduit securely bracketed?

2. Duct and plenum covered w/correct nozzles?  
☒ Yes ☐ No ☐ N/A

4. System installed in accordance w/unfg. UL listing?  
☒ Yes ☐ No ☐ N/A

6. Seals intact no evidence of tampering?  
☒ Yes ☐ No ☐ N/A

8. Pressure gauge in proper range?  
☒ Yes ☐ No ☐ N/A

10. Inspected cylinder and mounting brackets?  
☒ Yes ☐ No ☐ N/A

12. Tested for proper operation from remote?  
☒ Yes ☐ No ☐ N/A

14. Checked operation of gas valve?  
☒ Yes ☐ No ☐ N/A

16. Proper nozzle covers in place?  
☒ Yes ☐ No ☐ N/A

18. Checked travel of cable nuts/s-hooks?  
☒ Yes ☐ No ☐ N/A

20. Proper separation between fryers and flame?



**PROTEGIS**  
I R S

Protegis Fire & Safety  
2801 East S.R. 60  
Valrico, FL 33594  
Phone: 877-662-3473

☒ Yes ☐ No ☐ N/A

21. Proper clearance flame to filters?  
☒ Yes ☐ No ☐ N/A

23. All filters put back in place?  
☒ Yes ☐ No ☐ N/A

25. Manual and remote set/seals in place?  
☒ Yes ☐ No ☐ N/A

27. System operation and seals in place?  
☒ Yes ☐ No ☐ N/A

29. Clean cylinder and mount?  
☒ Yes ☐ No ☐ N/A

31. Personnel instructed on system operation?  
☒ Yes ☐ No ☐ N/A

33. Extinguishers properly serviced?  
☒ Yes ☐ No ☐ N/A

35. Did fire alarm actuate as intended?  
☒ Yes ☐ No ☐ N/A

**Explanation of "No" Answers**

Any "No" answers must be explained using the comment specific for each question. Additional comments can be added here.  
Please see the summary section at the top of the form for the comments.

☒ System is installed in accordance with manufacturers instruction NFPA 17 or 17A and or 96 sections applicable to fire suppression systems only  
Florida regulations 69A-21 and 633.

The pre-engineered state certified fire systems tech. certifies that he personally inspected and surveyed the system and has found the conditions to be as stated on this report. This system did not pass survey. Warning: Failure to correct all deficiencies may cause loss of life and or property. See Deficiency Summary Section.

**Tester Information**

Frequency:  
Semi-Annual

Inspected By:  
CHRIS LETO

Date of Test:  
11/13/2020

Tester Signature:

Certification Number:  
FEP20-000056

Customer Signature:

Customer Name:  
Robert Bargholz

**Hood Fire Suppression System Inspection Report**



**PROTEGIS**  
F A E Y

**Location Code:** PMNPSQS

**Contact:** Jon Wietzel

**Contact Address:** 520 N FALKENBURG RD  
TAMPA, FL 33619-7884

**Phone:** 813-247-8074

**Email:**

**Property Evaluated:** Falkenburg Rd Jail (Detention and  
Correctional)

520 N FALKENBURG RD  
TAMPA, FL 33619-7884

**Description:** Hood (BUCKEYE #4&5)

**Company:** Protegis Fire & Safety

**Address:** 2801 East S.R. 60  
Valrico, FL 33594

**Company Phone:** 877-662-3473

**Inspector:** CHRIS LETO  
FEP20-000056

**Date of Work:** 11/13/2020

**Frequency:** Semi-Annual

---

**Attached Files**

There are no attachments for this submission

---

**Deficiency Summary**

There are no reported deficiencies for this submission

---

**General Comments**

There are no general comments for this submission

**PROTEGIS**

Protegis Fire & Safety  
 2801 East S.R. 60  
 Valrico, FL 33594  
 Phone: 877-662-3473

## Hood Fire Suppression System Inspection Report

### Account Information

Facility Name: Falkenburg Rd Jail	Property Type: Detention and Correctional	Assembly Description: Hood (BUCKEYE #2)
Service Address: 520 N FALKENBURG RD, TAMPA, FL, 33619-7884		
Mailing Name: Jon Wietzel	Phone: 813-247-8074	
Mailing Address: 520 N FALKENBURG RD, TAMPA, FL, 33619-7884		

### Hood Inspection Information

Serial # 24459FQ	Mfg BUCKEYE	Model BFR 10
<input type="checkbox"/> Recharge	<input type="checkbox"/> Install	<input type="checkbox"/> Repipe
<input type="checkbox"/> Hydro	<input checked="" type="checkbox"/> Wet	<input type="checkbox"/> Dry
Other		
Location Of Cylinder ABOVE COOLER		
Master Cyl. Size BFR 10	Slave Size Na	Slave Size Na
Mfg. Date 2017	Hydro. Date Na	Last Recharge Na
Fuel Shut Off <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	Electric <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	Gas <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
360° Links 4	450° Links	500° Links
Duct Size(s) 10" (4)	Plenum Size(s) 6' x 16" 6' (4)	Size 2.5 inch
Other Links		

### Appliances (Left to Right)

RACK OVEN (4)
---------------

1. All appliances properly covered w/correct nozzles?  
☒ Yes ☐ No ☐ N/A
2. Duct and plenum covered w/correct nozzles?  
☒ Yes ☐ No ☐ N/A
3. Checked positioning of all nozzles?  
☒ Yes ☐ No ☐ N/A
4. System installed in accordance w/mfg. UL listing?  
☒ Yes ☐ No ☐ N/A
5. Hood/duct penetrations sealed w/weld or UL device?  
☒ Yes ☐ No ☐ N/A
6. Seals intact no evidence of tampering?  
☒ Yes ☐ No ☐ N/A
7. If system discharged are seals broken?  
☐ Yes ☐ No ☒ N/A
8. Pressure gauge in proper range?  
☒ Yes ☐ No ☐ N/A
9. Checked cartridge weight?  
☒ Yes ☐ No ☐ N/A
10. Inspected cylinder and mounting brackets?  
☒ Yes ☐ No ☐ N/A
11. Operate system from terminal link?  
☒ Yes ☐ No ☐ N/A
12. Tested for proper operation from remote?  
☒ Yes ☐ No ☐ N/A
13. Checked micro switch operation?  
☒ Yes ☐ No ☐ N/A
14. Checked operation of gas valve?  
☒ Yes ☐ No ☐ N/A
15. Clean nozzles?  
☒ Yes ☐ No ☐ N/A
16. Proper nozzle covers in place?  
☒ Yes ☐ No ☐ N/A
17. Replaced links?  
☒ Yes ☐ No ☐ N/A
18. Checked travel of cable nuts/s-hooks?  
☒ Yes ☐ No ☐ N/A
19. Piping and conduit securely bracketed?  
☒ Yes ☐ No ☐ N/A
20. Proper separation between fryers and flame?  
☐ Yes ☐ No ☒ N/A
21. Proper clearance flame to filters?  
☐ Yes ☐ No ☒ N/A
22. Exhaust fan operating?  
☒ Yes ☐ No ☐ N/A
23. All filters put back in place?
24. Fuel shut-off in on position?



**PROTEGIS**  
FIRE & SAFETY

Protegis Fire & Safety  
2801 East S.R. 60  
Valrico, FL 33594  
Phone: 877-662-3473

☒ Yes ☐ No ☐ N/A

25. Manual and remote set/seals in place?

☒ Yes ☐ No ☐ N/A

27. System operation and seals in place?

☒ Yes ☐ No ☐ N/A

29. Clean cylinder and mount?

☒ Yes ☐ No ☐ N/A

31. Personnel instructed on system operation?

☒ Yes ☐ No ☐ N/A

33. Extinguishers properly serviced?

☒ Yes ☐ No ☐ N/A

35. Did fire alarm actuate as intended?

☒ Yes ☐ No ☐ N/A

**Explanation of "No" Answers**

Any "No" answers must be explained using the comment specific for each question. Additional comments can be added here.  
Please see the summary section at the top of the form for the comments.

☒ System is installed in accordance with manufacturers instruction NFPA 17 or 17A and or 96 sections applicable to fire suppression systems only.  
Florida regulations 69A-21 and 633.

☐ The pre-engineered state certified fire systems tech. certifies that he personally inspected and surveyed the system and has found the conditions to be as stated on this report. This system did not pass survey. Warning: Failure to correct all deficiencies may cause loss of life and or property. See Deficiency Summary Section.

**Tester Information**

Frequency:  
Semi-Annual

Inspected By:  
CHRIS LETO

Date of Test:  
11/13/2020

Tester Signature:

Certification Number:  
FEP20-000056

Customer Signature:

Customer Name:  
Robert Bargholz